

Village Maintenance Report

To: Mayor David Miller

CC: Deputy Mayor Larry Chaleff and Village Trustees

From: Brian Gauger, Motor Equipment Operator

Date: December 27, 2021

Re: December Maintenance Report

1. **Equipment Maintenance:** We cut out the rusted-out metal from the sides of the Ford dump body, made new panels and welded them in place. We also welded in a solid plate on the inside of the dump body to support the side walls. This was a very time intensive process which also helped preserve the dump body a little longer. The sander was then able to be installed and tested. The plow for the 1993 International truck had its rubber edge replaced and the hydraulic hoses were also replaced due to dry-rot. The plow for the 2003 International truck had a lot of rusted-out metal behind the rubber edge so we cut the metal out, welded on two plates and redrilled the mounting holes for the edge. The plow lift piston on the 2003 truck's bracket broke off the bottom, we were able to clean and reweld it. We also replaced two hydraulic hoses from the piston to the main hydraulic block that were dry rotted.
2. **General Village Maintenance:** The leaves that were dumped at the pool have all been loaded out and taken to the dump of the town of North Hempstead. The entrances have all been blown out and bushes were trimmed down for the winter.
3. **Street Light Maintenance:** We were notified about two light outages. The first, was at the corner of Melbourne Rd. and Merrivale Rd., which was found to be a loose bulb. The second, was at 52 Tain Dr., which was found to be a bad LED bulb and was replaced and tested. The spot light on the entrance to the Joyce Cohn Pathway was found to be staying on all the time, the photocell was replaced and tested.